





Ensure DS-1 is positioned correctly and verify that DC-B23/24 is installed on the appropriate side of the vehicle.




16





A#19

SCREW E = 4  
SCREW G = 1  
SCREW H = 1



SCREW E = 2








SCREW Q = 1



THE SIDE MIRRORS, AS IF SUSPENDED IN MID-AIR, THANKS TO THE AIRFOIL-SHAPED SUPPORT ARE SET APART FROM THE BODY FOR BETTER AERODYNAMIC PENETRATION, SHOWING THE METICULOUS OPTIMIZATION THAT WAS CARRIED OUT ON THEM IN THE WIND TUNNEL.





Ensure DS-1 is positioned correctly and verify that DC-B23/24 is installed on the appropriate side of the vehicle.



A#20




SCREW E = 4  
SCREW G = 1  
SCREW H = 1





SCREW E = 2




THE PAGANI UTOPIA'S BUTTERFLY DOORS SWING UPWARD AND OUTWARD, COMBINING STYLE AND EASE OF ACCESS. OPERATED BY FINGER LATCHES, THEY EMBODY PAGANI'S SEAMLESS BLEND OF ELEGANCE AND FUNCTIONALITY.






SCREW Q = 1

18



A#19


SCREW E = 1  
SCREW G = 1



SCREW E = 1  
SCREW G = 1





Improper alignment of components beneath the hood or incorrect fastening of E screws (see page 37) may result in visible panel gaps.




A#1

19



SCREW A = 2  
SCREW G = 1



A#1



SCREW C = 2  
SCREW E = 11