

Available (Sound) Profiles for HM DCC				16/01/2024		
SKU	Name	Scale	Brand	Live	ETA	Version
SD001	A1/A3	00	Hornby	Yes		[v0.2.0]
SD002	A4	00	Hornby	Yes		[v0.2.0]
SD003	Class 43 HST (Valenta)	00	Hornby	Yes		[v0.2.1]
SD004	Class 43 HST (MTU)	00	Hornby	Yes		[v0.2.1]
SD005	Class 91	00	Hornby	No	Q1 (2024)	
SD006	Class 73	00	Hornby	Yes		[v0.2.0]
SD007	Class 800	00	Hornby	No	Q1 (2024)	
SD008	P2	00	Hornby	Yes		[v0.2.0]
SD009	Class 08	00	Hornby	Yes		[v0.2.0]
SD010	A1: Tornado	00	Hornby	Yes		[v0.2.0]
SD011	Princess Coronation	00	Hornby	Yes		[v0.2.0]
SD012	Class 40	00	Hornby	No	Q4 (2024)	
SD013	Class 37	00	Hornby	Yes		[v0.1.0]
SD014	Class 71	00	Hornby	No	Q2 (2024)	
SD015	Class 67	00	Hornby	Yes		[v1.4.0]
SD016	2P	00	Hornby	Yes		[v0.2.0]
SD017	4F	00	Hornby	Yes		[v0.2.0]
SD018	Class 31	00	Hornby	Yes		[v0.2.0]
SD019	Britannia	00	Hornby	Yes		[v0.2.0]
SD020	Merchant Navy	00	Hornby	Yes		[v0.2.0]
SD021	S15	00	Hornby	Yes		[v0.2.0]
SD022	Class 50	00	Hornby	Yes		[v0.2.0]
SD023	Class 66	00	Hornby	Yes		[v0.2.0]
SD024	B12	00	Hornby	Yes		[v0.2.0]
SD025	W1	00	Hornby	No	Q1 (2024)	
SD026	9F	00	Hornby	Yes		[v0.2.0]
SD027	Class 423: 4 VEP	00	Hornby	No	Q1 (2024)	
SD028	Class 87	00	Hornby	No	Q2 (2024)	
SD029	Black 5	00	Hornby	Yes		[v0.2.0]
SD030	Class 755: Flirt	00	Hornby	No	Q2 (2024)	
SD031	Turbomotive	00	Hornby	Yes		[v0.1.0]
SD032	Class 55: Deltic	00	Hornby	Yes		[v0.2.0]
SD036	A1/A3: Flying Scotsman	TT	Hornby	Yes		[v0.2.0]
SD037	A1/A3	TT	Hornby	Yes		[v0.2.0]
SD038	A4	TT	Hornby	Yes		[v0.2.0]
SD040	A1/A3: Flying Scotsman	00	Hornby	Yes		[v0.2.0]
SD041	Class 43 HST (Valenta)	TT	Hornby	No	Q1 (2024)	
SD042	Class 56	00	Hornby	Yes		[v0.2.0]
SD043	Class 47	00	Hornby	Yes		[v0.1.0]
SD044	Class 43 HST (MTU)	TT	Hornby	No	Q1 (2024)	
SD045	Class 60	00	Hornby	Yes		[v1.4.1]
SD046	Class 66: Coronation	00	Hornby	Yes		[v0.1.0]
SD049	DP1: Deltic	00	Hornby	No	Q3 (2024)	
SD050	Class 50	TT	Hornby	No	Q1 (2024)	
SD051	Class 66	TT	Hornby	No	Q1 (2024)	
SD052	Duchess	TT	Hornby	No	Q1 (2024)	
SD053	Class B17/5: Streamline	00	Hornby	No	Q2 (2024)	
SD054	2MT	00	Hornby	Yes		[v1.5.0]
SD055	Class 370: APT	00	Hornby	No	Q2 (2024)	
SD056	Lion	00	Hornby	No	Q4 (2024)	
SD057	Class 37	TT	Hornby	No	Q2 (2025)	
SD058	Class 20	00	Hornby	No	Q3 (2024)	
SD059	King Class	00	Hornby	No	Q3 (2024)	
SD060	Class 121: DMU	00	Hornby	No	Q3 (2024)	
SD061	Hall Class	00	Hornby	No	Q4 (2024)	
SD062	B1 Class	00	Hornby	No	Q3 (2024)	
SD063	Class 153: DMU	00	Hornby	No	Q4 (2024)	
SD064	Class 803	00	Hornby	No	Q3 (2024)	
SD500	FS Class: E.656	00	Rivarossi	No	TBC	
SD999	Default Profile (TXS)	00/TT		Yes		[v0.2.0]

Patch ID	Patch Notes / Features
[0.1.0]	First Release
[0.1.1]	CV158: Global Volume reduction.
[0.2.0]	Stationary Power Bank Charging.
	ADCC / ABC CV127: Constant Braking Distance performance improvement.
	Bug Fix - Sound playback starts, but loco fails to move after a break in track power.
[0.2.1]	Function Masking Update - Locomotives with the same address have selected masking of sound functions depending on loco direction.
[1.4.0]	Bug Fix - CV29: Reverse Motor Control not working on Bluetooth Mode.
[1.5.0]	Minor Bug Fixes

Please proceed to re-download your chosen (Sound) Profile(s) to ensure that you have the latest version